

RhinoClean™

PRODUCT DATA SHEET

HR2400™ Haze Remover

Description

- Specially formulated liquid to remove imbedded U.V., conventional and plastisol inks (haze / ghost images) that remain on the screen following emulsion removal.
- Effectively lifts the haze and imbedded ink from the mesh then emulsifies and dissolves the ink resins, binders, pigments, plasticizers, etc.
- The solution suspends resins so reattachment to the mesh surface is prohibited, thus allowing for water-rinse removal.
- Excellent degreaser; it also removes dirt and residue.

Directions

1. Apply HR2400™ directly to both sides of a screen beginning in the center and working in a circular fashion until the whole screen is covered.
2. Let coating remain on screen for approximately 10 minutes.
3. To eliminate image, remove coating with a high pressure cleaner beginning from the bottom of screen and working to the top moving in a side to side motion.

It is the responsibility of the screen printer to test the product; review the MSDS prior to use to evaluate whether or not the product is correct for the application intended.